RAILROAD COMMISSION OF TEXAS HEARINGS DIVISION

OIL & GAS DOCKET NO. 20-0320455

IN RE: P-5 ORGANIZATION REPORT OF PETRO-SMITH OPERATING LLC

FINAL ORDER

The Commission finds that after notice and an opportunity for hearing regarding the captioned matter, the Operator failed to request a hearing and pay the hearing fee as required by 16 Tex. ADMIN. Code §3.15(g)(4) and Tex. NAT. Res. Code §89.022(f). This matter having been duly submitted to the Railroad Commission of Texas at conference held in its offices in Austin, Texas, the Commission makes the following findings of fact and conclusions of law.

FINDINGS OF FACT

- 1. Petro-Smith Operating LLC [Operator #660313] (the "Operator"), is the record operator or one or more inactive wells in the State of Texas and is required to file Organization Report (Form P-5) with the Commission. Operator's most recent P-5 was due on or before January 1, 2019.
- 2. After filing its most recent Organization Report (Form P-5) with the Commission, the Operator was notified they were deficient and had failed to comply with the requirements of 16 Tex. ADMIN. CODE § 3.15 (Surface Equipment Removal Requirements and Inactive Wells) and provided with a written statement of the reasons for the determination and allowed ninety (90) days from the date its P-5 was due to comply with the requirements of 16 Tex. ADMIN. CODE § 3.15 and Tex. NAT. Res. CODE §§89.021 89.030.
- 3. After the expiration of ninety (90) days and pursuant to 16 Tex. ADMIN CODE §3.15(g)(4), an authorized Commission employee determined that the Operator's Organization Report still could not be renewed because the Operator continued to fail to comply with the requirements of 16 Tex. ADMIN. CODE §3.15 (Surface Equipment Removal Requirements and Inactive Wells).
- 4. The Commission sent the Operator a letter by certified mail giving notice to the Operator of the determination of continued non-compliance regarding specified inactive wells, attached as Exhibit A to this order, and advising the Operator of the right to request a hearing to show compliance. The letter notified the Operator that the hearing request must be received in docket services no later than 30 days after the date of the letter. The letter also notified the Operator that a final order denying renewal of the Operator's

Organization Report (Form P-5) would result in the cancellation of all P-4 Certificates of Compliance and the severance of all pipeline or other carrier connections.

- 5. All notices and letters from the Commission to the Operator on this matter were addressed and mailed to the Operator's most recently reported address on the Form P-5 Organization Report.
- 6. The Operator did not timely request a hearing and pay the hearing fee on these issues as required under 16 Tex. ADMIN. CODE §3.15(g)(4) (Surface Equipment Removal Requirements and Inactive Wells).
- 7. Statewide Rule 15 (16 Tex. ADMIN. CODE §3.15) is a Commission rule that relates to safety or the prevention or control of pollution.

CONCLUSIONS OF LAW

- 1. The Operator received proper notice and an opportunity for hearing regarding compliance with 16 Tex. Admin. Code §3.15 and Tex. Nat. Res. Code §§89.021 89.030.
- 2. All things necessary to the Commission attaining jurisdiction over the subject matter and the parties in this matter have been performed or have occurred.
- 3. The Operator is in violation of Commission Statewide Rule 15 and did not timely request a hearing to contest the determination that it was in violation.
- 4. The Operator's P-5 Organization Report should not be renewed and all the Operator's P-4 Certificates of Compliance should be cancelled, with all related pipeline or other carrier connections severed. 16 Tex. Admin. Code §3.15 (g)(4) and Tex. Nat. Res. Code §§89.022(f), 91.704 91.706.
- 5. The Operator's P-5 Organization Report cannot be renewed until the operator brings the inactive wells shown on the attached Exhibit A into compliance with the requirements of 16 Tex. Admin. Code §3.15 and Tex. Nat. Res. Code §§89.021 89.030.

IT IS ORDERED that renewal of Petro-Smith Operating LLC's P-5 Organization Report is hereby **DENIED**.

It is further ORDERED that all P-4 Certificates of Compliance issued to Petro-Smith Operating LLC as operator of record are hereby **CANCELLED** and all related pipeline or other carrier connections are hereby **SEVERED**.

It is further ORDERED that Petro-Smith Operating LLC shall bring the wells on Exhibit A into compliance with Statewide Rule 15 (16 Tex. ADMIN. CODE §3.15) and that the Operator's P-5 Organization Report shall not be renewed until the wells on Exhibit A have been brought into compliance as required by this order.

It is further ORDERED that Petro-Smith Operating LLC and each person who held a position of ownership or control in the Operator at the time the Operator's most-recent P-5 Organization Report was filed shall be subject to the terms of Tex. NAT. Res. Code §91.114.

It is further ORDERED by the Commission that this order shall not be final and effective until 25 days after the Commission's Order is signed, unless the time for filing a motion for rehearing has been extended under Tex. Gov't Code §2001.142, by agreement under Tex. Gov't Code §2001.147, or by written Commission Order issued pursuant to Tex. Gov't Code §2001.146(e). If a timely motion for rehearing is filed by any party at interest, this order shall not become final and effective until such motion is overruled, or if such motion is granted, this order shall be subject to further action by the Commission. Pursuant to Tex. Gov't Code §2001.146(e), the time allotted for Commission action on a motion for rehearing in this case prior to its being overruled by operation of law is hereby extended until 100 days from the date the Commission Order is signed.

All requested Findings of Fact and Conclusions of Law which are not expressly adopted herein are **DENIED**. All pending motions and request for relief not previously granted or granted herein are **DENIED**.

RAILROAD COMMISSION OF TEXAS

(Signatures affixed by Rule 15 Inactive Well Master Order dated June 18, 2019.)

API	Number Di	strict	ID Number	Lease Name	Well Number
047	32271 No approved	04 W-3X on	238512 file Operations is	MYRICK ssue preventing 14(B)(2) approval	2
199	32550 No approved	03	132536		9
239	00943 No approved		054128 file	KRAMER #3	1
239	00949 No approved		00842 file	KRAMER #2	1
239	32300 No approved Must resolv	02 W-3X on e Field (file	WEBERNICK G.U. -15 delinquency preventing 14B2 a	1 pproval
239	32407 No approved		09235 file	KRAMER	1
239	33525 No approved		09235 file	KRAMER	1 A
241	30431 No approved		118384 file	HANKAMER ET AL	1
241	No approved	03 W-3X on e Field (file	HANKAMER ET AL -15 delinquency preventing 14B2 a	2 pproval
241	30441 Electricity No approved	03 must be W-3X on	119194 disconnected file	HANKAMER ET AL d (certify on Form W-3C) -15 delinquency preventing 14B2 a	3
241	30453 Electricity No approved	must be	disconnected	HANKAMER SWD d (certify on Form W-3C)	1
241	30814 Electricity No approved	must be	disconnected	HANKAMER ET AL d (certify on Form W-3C)	8
289	31331 Electricity No approved			FORTSON l (certify on Form W-3C)	1
	No approved	04 W-3X on e Field C	file	WILSON, E. C. -15 delinquency preventing 14B2 a	10 pproval
	04011 No approved		151773 file	BAYDER, E.	12
	32457 No approved	04 W-3X on		BAYDER-MONTGOMERY, E.	13

Docket No. 20-0320455 Exhibit A

API	Number Di	strict	ID Number	Lease Name	Well Number
409	32591 No approved			BAYDER-MONTGOMERY, E.	14
409	32673 No approved			MARTINEZ/SCHMIDT UNIT	1
457	00218 No approved			BROWN, WM. S., FEE	1D
457	30004 No approved			BROWN, WM. S., FEE	12
479	No approved	W-3X on	file	STAGGS-STATE -15 delinquency preventing 14B2 ap	2 proval
479		must be	disconnected	STAGGS-STATE d (certify on Form W-3C)	4
479	35860 No approved			DE LA GARZA MINERAL TRUST	8
479	36200 No approved			DE LA GARZA MINERAL TRUST	9
479		must be	disconnected	STAGGS STATE d (certify on Form W-3C)	5

Docket No. 20-0320455

Exhibit A